


3 Panel 29 1/2" = 1'-0"


> Lbl Qty Member Length C0 3 362S125-18 11 3/8"

Bill of Material 3/8" = 1'-0"





Lbl Qty Member Length C0 4 362S125-18 11 3/8" T0 2 362T100-18 4' - 2 7/8"

Bill of Material 3/8" = 1'-0"




Lbl Qty Member Length C0 3 362S125-18 11 3/8" 362T100-18 2' - 7 3/8"










5 Panel 32 1/2" = 1'-0"

Lbl Qty Member Length C0 4 362S125-18 11 3/8" T0 2 362T100-18 4' - 5 1/4"

Bill of Material 3/8" = 1'-0"



Lbl Qty Member Length C0 3 362S125-18 11 3/8" T0 2 362T100-18

8	Panel 34	
	1/2" = 1'-0"	

Lbl Qty Member Length 11 3/8" 2' - 10 1/2"

 $13 \overline{) \frac{\text{Bill of Material}}{3/8" = 1'-0"}}$

TRANSCON Review		Marriott Courtyard Sailisbury , NC		Panel29-34			
STEEL		Drawn by	Scale	Date	Size	Project number	Drawing number
FRAMING THE FUTURE			As indicated	07/12/12	Α	12-105	2.13

THE DRAWINGS HEREIN ARE MANUFACTURING DRAWINGS ONLY. CONTRACTOR SHALL BE SOLELY RESPONSIBLE FOR VERIFYING ALL DIMENSIONS, SITE CONDITIONS, AND THAT ALL STATE AND LOCAL CODE REQUIREMENTS ARE MET. PLEASE CONTACT TRANSCON STEEL FOR ANY ADDITIONAL CLARITY IN NEEDED PRIOR TO INSTALLATION.